



Note:  
RCD: .xxx+-.xxx STD: .xxx+-.xxx ST Key Dimension:\*

1 RCD: Required Control Dimension ,These Dimensions need Process control & capability(initial and ongoing), 100%inspection, poke yoke, etc.as appropriate.

2 STD: Statistically Toleranced Dimension ,These Dimensions need demonstration of ongoing process capability (CpK/PpK).

3 Key Dimension: These Dimensions are defined by ME/Mfg, and need inspection as appropriate.

If you want more information, please review the criterions of 《TC-RDW-18》 and 《TC-QAW-40》