



Note:
RCD: 0000+000 STD: 000+000 00 Key Dimension:*
1 RCD: Required Control Dimension ,These Dimensions need Process control & capability(initial and ongoing), 100%inspection, poke yoke, etc.as appropriate.
2 STD: Statistically Toleranced Dimension ,These Dimensions need demonstration of ongoing process capability (CpK/PpK).
3 Key Dimension: These Dimensions are defined by ME/Mfg, and need inspection as appropriate.
If you want more information, please review the criterions of 《TC-RDW-18》 and 《TC-QAW-40》