



Note:  
 RCD: STD: Key Dimension: \*  
 1 RCD: Required Control Dimension ,These Dimensions need Process control & capability(initial and ongoing), 100%inspection, poke yoke, etc.as appropriate.  
 2 STD: Statistically Toleranced Dimension ,These Dimensions need demonstration of ongoing process capability (CpK/PpK).  
 3 Key Dimension : These Dimensions are defined by ME/Mfg , and need inspection as appropriate.  
 If you want more information , please review the criterions of 《TC-RDW-18》 and 《TC-QAW-40》

TITLE	Antares 1K/1.5K OUTLINE DRAWING	DRAW	NICOLE SUN 2016-07-26
PART NO.	F9103-537500-00P	DESIGN	NICOLE SUN 2016-07-26
MATERIAL	SEE NOTES	CHECKED	
COATING	SEE NOTES	SAFETY	RACHELL YUAN 2016-07-26
UNITS	mm	APPROVED	BENNETT FEI 2016-07-26
SHEET	1/1	SCALE 1:1 <b>EATON</b> ELECTRICAL SECTOR	

Us:frs E2012815 (Sum, Nicole) 2016/8/30 10:54:52